

Elements of
METALLURGY and
ENGINEERING
ALLOYS

Edited by
F.C. Campbell

Thu Vien DHKTCN-TN



KNV.13000433

ASM
INTERNATIONAL
®
The Materials
Information Society

Contents

Preface	xiii
Part I: Physical and Mechanical Metallurgy	1
Chapter 1 Metallic Structure	3
1.1 Periodic Table	3
1.2 Bonding in Solids	4
1.2.1 Metallic Bonding	5
1.2.2 Ionic Bonding	7
1.2.3 Covalent Bonding	7
1.2.4 Secondary Bonding	8
1.3 Crystalline Structure	8
1.3.1 Space Lattices and Crystal Systems	8
1.3.2 Face-Centered Cubic System	9
1.3.3 Hexagonal Close-Packed System	9
1.3.4 Body-Centered Cubic System	11
1.4 Slip Systems	12
1.5 Allotropy	14
Chapter 2 Crystalline Imperfections and Plastic Deformation	17
2.1 Point Defects	17
2.2 Line Defects	18
2.3 Plastic Deformation	20
2.3.1 Dislocations and Plastic Flow	24
2.3.2 Work Hardening	27
2.4 Surface or Planar Defects	27
2.4.1 Grain Boundaries	29
2.4.2 Polycrystalline Metals	30
2.4.3 Phase Boundaries	34
2.4.4 Twinning	35
2.4.5 Stacking Faults	38
2.5 Volume Defects	39
Chapter 3 Solid Solutions	41
3.1 Interstitial Solid Solutions	42
3.2 Substitutional Solid Solutions	43
3.3 Ordered Structures	45
3.4 Intermediate Phases	47
3.5 Dislocation Atmospheres and Strain Aging	49

Chapter 4 Introduction to Phase Transformations	53
4.1 Free Energy	53
4.2 Kinetics	54
4.3 Liquid-Solid Phase Transformations	55
4.4 Solid-State Phase Transformations	57
4.5 Spinodal Decomposition	60
4.6 Martensitic Transformation	61
Chapter 5 Diffusion	63
5.1 Mechanisms of Diffusion	64
5.1.1 Interstitial Diffusion	64
5.1.2 Substitutional Diffusion	64
5.2 Fick's Laws of Diffusion	65
5.2.1 Fick's First Law of Diffusion	66
5.2.2 Fick's Second Law of Diffusion	66
5.2.3 Several Applications of Fick's Second Law of Diffusion	67
5.3 Temperature Dependence of Diffusion	70
5.4 Intrinsic Diffusion Coefficients (Kirkendall Effect)	71
5.5 High Diffusion Paths	72
Chapter 6 Phase Diagrams	75
6.1 Phase Rule	75
6.2 Binary Isomorphous System	76
6.3 Eutectic Alloy Systems	81
6.3.1 Aluminum-Silicon Eutectic System	82
6.3.2 Lead-Tin Eutectic System	84
6.4 Free Energy of Alloy Systems	85
6.5 Peritectic Reaction	87
6.6 Monotectic Reaction	88
6.7 Intermediate Phases	89
6.8 Solid-State Reactions	90
6.8.1 Eutectoid Reaction	91
6.9 Ternary Phase Diagrams	92
Chapter 7 Solidification and Casting	95
7.1 The Liquid State	95
7.2 Solidification Interfaces	95
7.3 Solidification Structures	98
7.4 Segregation	101
7.5 Grain Refinement and Secondary Dendrite Arm Spacing	103
7.6 Porosity and Shrinkage	104
7.7 Casting Processes	107
7.7.1 Sand Casting	107
7.7.2 Plaster and Shell Molding	109
7.7.3 Evaporative Pattern Casting	109
7.7.4 Investment Casting	110
7.7.5 Permanent Mold Casting	112
7.7.6 Die Casting	112
Chapter 8 Recovery, Recrystallization, and Grain Growth	117
8.1 Recovery	119
8.2 Recrystallization	122
8.2.1 Recrystallization—Temperature and Time	125
8.2.2 Recrystallization—Degree of Cold Work	126

8.2.3 Recrystallization—Purity of Metal	128
8.2.4 Recrystallization—Original Grain Size	128
8.2.5 Recrystallization—Temperature of Deformation	129
8.3 Grain Growth	129
8.3.1 Normal Grain Growth	129
8.3.2 Abnormal Grain Growth	130
Chapter 9 Precipitation Hardening	135
9.1 Particle Hardening	135
9.2 Theory of Precipitation Hardening	136
9.3 Precipitation Hardening of Aluminum Alloys	138
9.3.1 Solution Heat Treating	143
9.3.2 Quenching	144
9.3.3 Aging	145
9.4 Dispersion Hardening	148
Chapter 10 The Iron-Carbon System	153
10.1 Ferrite	154
10.2 Eutectoid Structures	155
10.3 Hypoeutectoid and Hypereutectoid Structures	158
10.4 Nonequilibrium Cooling—TTT Diagrams	162
10.5 Bainite	165
10.5.1 Upper Bainite	167
10.5.2 Lower Bainite	167
10.6 Martensite	169
10.6.1 Formation of Martensite in Steels	170
10.6.2 Morphology of Martensite	172
10.7 Retained Austenite	173
10.8 Carbon Content	173
Chapter 11 Heat Treatment of Steel	177
11.1 Annealing	178
11.2 Process Annealing and Stress Relief	178
11.3 Normalizing	179
11.4 Spheroidizing	179
11.5 Hardening	180
11.5.1 Continuous Cooling Transformation Diagrams	180
11.5.2 Austenitizing	182
11.5.3 Quenching	184
11.5.4 Hardenability	185
11.5.5 Prediction of Hardenability	186
11.5.6 Effect of Grain Size	188
11.5.7 Effect of Alloying Elements	191
11.5.8 Tempering	191
11.6 Interrupted Quenching	194
11.6.1 Martempering	195
11.6.2 Austempering	196
11.7 Temper Embrittlement	197
11.7.1 Tempered Martensite Embrittlement	197
11.7.2 Temper Embrittlement	197

Chapter 12 Mechanical Behavior	201
12.1 Tension	201
12.1.1 Engineering Stress-Strain Curve	201
12.1.2 Ductility	205
12.1.3 Resilience	206
12.1.4 Toughness	206
12.1.5 True Stress-Strain Curve	206
12.2 Stress Concentrations	209
12.3 Notched Tensile Test	210
12.4 Compression	211
12.5 Shear	213
12.6 Stress-Strain Relationships	213
12.7 Combined Stresses	213
12.8 Yield Criteria	214
12.9 Residual Stresses	215
12.10 Hardness	217
Chapter 13 Fracture	221
13.1 The Brittle Fracture Problem	221
13.2 Brittle and Ductile Fracture	222
13.3 Ductile-to-Brittle Transition Testing	224
13.4 Griffith Theory of Brittle Fracture	229
13.5 Fracture Mechanics	231
13.6 Plasticity Corrections	233
13.7 Plane-Strain Fracture Toughness Testing	233
13.8 Fracture Toughness of Engineering Alloys	237
Chapter 14 Fatigue	243
14.1 Stress Cycles	243
14.2 High-Cycle Fatigue	244
14.3 Low-Cycle Fatigue	246
14.4 Cumulative Damage	251
14.5 Fatigue Crack Nucleation and Growth	252
14.6 Fatigue Crack Propagation	252
14.7 Crack Closure	255
14.8 Geometrical Stress Concentrations	256
14.9 Manufacturing Stress Concentrations	257
14.10 Environmental Effects	258
14.11 Fatigue Life Improvement	260
14.12 Fatigue Design Methodologies	262
Chapter 15 Creep	265
15.1 The Creep Curve	265
15.2 Stress-Rupture Test	268
15.3 Creep Deformation Mechanisms	269
15.4 Elevated-Temperature Fracture	271
15.5 Metallurgical Instabilities	273
15.6 Creep Life Prediction	273
15.7 Creep-Fatigue Interaction	274
15.8 Design Against Creep	276
Chapter 16 Deformation Processing	279
16.1 Hot Working	280
16.2 Cold Working	282

16.3	Rolling	283
16.4	Forging	285
16.5	Extrusion	291
16.6	Sheet Metal Forming Processes	293
16.7	Blanking and Piercing	293
16.8	Bending	293
16.9	Stretch Forming	295
16.10	Drawing	296
16.11	Rubber Pad Forming	297
16.12	Superplastic Forming	297
Chapter 17 Physical Properties of Metals		303
17.1	Density	303
17.2	Thermal Properties	304
17.2.1	Melting and Boiling Points	304
17.2.2	Thermal Expansion	304
17.2.3	Heat Capacity and Specific Heat Capacity	304
17.2.4	Thermal Conductivity	305
17.2.5	Thermal Diffusivity	306
17.2.6	Thermal Stresses	306
17.3	Band Theory of Metals	306
17.4	Electrical Properties	310
17.4.1	Electron Mobility	310
17.4.2	Electrical Resistivity	311
17.4.3	Electrical Conductor Alloys	311
17.5	Magnetic Properties	312
17.5.1	Magnetic Fields	312
17.5.2	Magnetic Induction	313
17.5.3	Magnetic Permeability	313
17.5.4	Magnetic Susceptibility	313
17.5.5	Types of Magnetism	314
17.5.6	Magnetic Domains	315
17.5.7	Magnetically Soft Materials	317
17.5.8	Magnetically Hard Materials	320
17.6	Optical Properties	321
Chapter 18 Corrosion		323
18.1	Basics of Electrochemical Corrosion	323
18.2	Forms of Corrosion	327
18.2.1	Uniform Corrosion	327
18.2.2	Galvanic Corrosion	328
18.2.3	Pitting	328
18.2.4	Crevice Corrosion	330
18.2.5	Erosion-Corrosion	331
18.2.6	Cavitation	332
18.2.7	Fretting Corrosion	332
18.2.8	Intergranular Corrosion	333
18.2.9	Exfoliation	334
18.2.10	Dealloying Corrosion	336
18.2.11	Stress-Corrosion Cracking	337
18.2.12	Corrosion Fatigue	338
18.2.13	Hydrogen Damage	339

18.3 Corrosion Prevention	340
18.3.1 Conditioning the Metal	340
18.3.2 Conditioning the Corrosive Environment	342
18.3.3 Electrochemical Control	342
18.4 High-Temperature Oxidation and Corrosion	343
Part II: Engineering Alloys	347
Chapter 19 Plain Carbon Steels	349
19.1 Brief History of Steel	350
19.2 Steel Production	351
19.3 Ironmaking	351
19.4 Steelmaking	353
19.4.1 Basic Oxygen Furnace	353
19.4.2 Electric Arc Furnace	354
19.4.3 Ladle Metallurgy	355
19.4.4 Residual Elements and Cleanliness	355
19.4.5 Ingot Casting	356
19.4.6 Continuous Casting	357
19.5 Hot Rolling	358
19.5.1 Plate Mills	359
19.5.2 Strip Mills	359
19.5.3 Long Product Mills	359
19.6 Cold Rolling and Drawing	359
19.7 Classification and Specifications for Steels	361
19.8 Plain Carbon Steels	361
19.9 Low-Carbon Steels	365
19.9.1 Low-Carbon Sheet Steels	365
19.9.2 Low-Carbon Structural Steels	367
19.10 Medium-Carbon Plain Carbon Steels	367
19.11 High-Carbon Plain Carbon Steels	368
19.12 Corrosion of Iron and Steel	369
19.13 Corrosion-Resistant Coatings	369
Chapter 20 Alloy Steels	371
20.1 Effects of Alloying Elements	371
20.2 Low-Alloy Structural Steels	375
20.2.1 Hot Rolled Carbon-Manganese Structural Steels	375
20.2.2 Heat Treated Carbon-Manganese Structural Steels	376
20.2.3 High-Nickel Steels for Low-Temperature Service	376
20.3 SAE/AISI Alloy Steels	377
20.3.1 Manganese Steels (13xx)	377
20.3.2 Chromium Steels (5xxx)	378
20.3.3 Molybdenum Steels (40xx)	378
20.3.4 Chromium-Molybdenum Steels (41xx)	378
20.3.5 Nickel-Chromium-Molybdenum Steels (43xx and 8xxx)	378
20.4 High-Fracture-Toughness Steels	382
20.5 Maraging Steels	383
20.6 Austenitic Manganese Steels	385
20.7 High-Strength Low-Alloy Steels	387
20.8 Dual-Phase Steels	390
20.9 TRIP Steels	391

Chapter 21 Surface Hardening of Steel	395
21.1 Surface Hardening by Localized Heat Treatment	395
21.1.1 Flame Hardening	395
21.1.2 Induction Hardening	395
21.2 Case Hardening	396
21.3 Carburizing	397
21.3.1 Pack Carburizing	397
21.3.2 Liquid Carburizing	398
21.3.3 Gas Carburizing	398
21.3.4 Vacuum Carburizing	401
21.3.5 Plasma (Ion) Carburizing	402
21.4 Nitriding	403
21.4.1 Gas Nitriding	404
21.4.2 Liquid Nitriding	405
21.5 Carbonitriding	405
21.6 Hardfacing	406
21.7 Other Surface-Hardening Processes	408
Chapter 22 Tool Materials	411
22.1 Water-Hardening Steels	413
22.2 Shock-Resisting Steels	415
22.3 Cold Work Steels	415
22.3.1 Oil-Hardening Cold Work Steels (Group O)	416
22.3.2 Air-Hardening, Medium-Alloy, Cold Work Steels (Group A)	417
22.3.3 High-Carbon, High-Chromium, Cold Work Steels (Group D)	418
22.4 Hot Work Steels	418
22.4.1 Chromium Hot Work Steels	418
22.4.2 Tungsten Hot Work Steels	419
22.4.3 Molybdenum Hot Work Steels	420
22.5 Low-Alloy Special-Purpose Steels	420
22.6 Mold Steels	420
22.7 High-Speed Steels	421
22.7.1 Molybdenum High-Speed Steels	423
22.7.2 Tungsten High-Speed Steels	424
22.8 Powder Metallurgy Tool Steels	425
22.9 Cemented Carbides	427
22.10 Cutting Tool Coatings	428
Chapter 23 Stainless Steels	433
23.1 Argon Oxygen Decarburization	434
23.2 Ferritic Stainless Steels	435
23.3 Martensitic Stainless Steels	438
23.4 Austenitic Stainless Steels	441
23.5 Duplex Stainless Steels	445
23.6 Precipitation-Hardening Stainless Steels	446
23.7 Cast Stainless Steels	447
23.8 Schaeffler Constitution Diagram	450
Chapter 24 Cast Irons	453
24.1 White Cast Iron	456
24.2 Gray Cast Iron	457
24.3 Ductile Cast Iron	464
24.4 Malleable Cast Iron	465

24.5	Compacted Graphite Iron	467
24.6	Alloy Cast Irons	467
Chapter 25	Copper	469
25.1	Copper Production	470
25.2	Wrought Copper Alloys	471
25.3	Pure Coppers	472
25.4	Copper Alloys	473
25.5	Brasses	474
25.6	Bronzes	478
25.7	Copper-Nickel Alloys	482
25.8	Beryllium-Copper	483
25.9	Copper Casting Alloys	484
25.10	Corrosion	485
Chapter 26	Aluminum	487
26.1	Aluminum Metallurgy	487
26.2	Aluminum Alloy Designation	488
26.3	Aluminum Alloys	491
26.3.1	Wrought Non-Heat-Treatable Alloys	491
26.3.2	Wrought Heat Treatable Alloys	493
26.4	Melting and Primary Fabrication	497
26.4.1	Rolling Plate and Sheet	498
26.4.2	Extrusion	501
26.5	Casting	501
26.5.1	Aluminum Casting Alloys	501
26.5.2	Aluminum Casting Control	504
26.6	Heat Treating	505
26.6.1	Annealing	505
26.7	Fabrication	506
26.8	Corrosion	506
Chapter 27	Magnesium and Zinc	509
27.1	Magnesium Metallurgy	509
27.2	Magnesium Alloy Designation	512
27.3	Magnesium Casting Alloys	512
27.3.1	Magnesium-Aluminum-Base Casting Alloys	513
27.3.2	Magnesium-Zirconium-Base Casting Alloys	515
27.4	Wrought Magnesium Alloys	517
27.5	Magnesium Heat Treating	519
27.6	Magnesium Fabrication	520
27.7	Magnesium Corrosion Protection	521
27.8	Zinc	521
27.9	Zinc Casting Alloys	523
27.10	Wrought Zinc Alloys	524
Chapter 28	Titanium	527
28.1	Titanium Metallurgy	527
28.2	Titanium Alloys	529
28.2.1	Commercially Pure Titanium	529
28.2.2	Alpha and Near-Alpha Alloys	531
28.2.3	Alpha-Beta Alloys	532
28.2.4	Beta Alloys	534

28.3 Melting and Primary Fabrication	535
28.3.1 Melting	536
28.3.2 Primary Fabrication	537
28.4 Forging	537
28.5 Casting	538
28.6 Heat Treating	539
28.6.1 Stress Relief	540
28.6.2 Annealing	541
28.6.3 Solution Treating and Aging	541
28.6.4 Heat Treating Control	543
28.7 Fabrication	543
Chapter 29 Nickel and Cobalt	547
29.1 Melting of Nickel	547
29.2 Nickel Metallurgy	547
29.3 Nickel Alloys	548
29.3.1 Corrosion- and Heat-Resistant Nickel Alloys	548
29.3.2 Specialty Nickel Alloys	554
29.4 Iron-Nickel Alloys	556
29.5 Cobalt and Cobalt Alloys	557
29.5.1 Cobalt-Base Wear-Resistant Alloys	557
29.5.2 Corrosion-Resistant Cobalt Alloys	559
Chapter 30 Superalloys	563
30.1 Superalloy Metallurgy	564
30.2 Commercial Superalloys	567
30.2.1 Nickel-Base Superalloys	567
30.2.2 Iron-Nickel-Base Superalloys	569
30.2.3 Cobalt-Base Superalloys	570
30.3 Melting and Primary Fabrication	570
30.3.1 Melting	570
30.3.2 Wrought Alloy Primary Fabrication	572
30.3.3 Powder Metallurgy Fabrication	573
30.4 Heat Treatment	573
30.4.1 Annealing	573
30.4.2 Precipitation Hardening	575
30.4.3 Cast Superalloy Heat Treatment	577
30.5 Fabrication	577
30.6 Coating Technology	578
Chapter 31 Refractory Metals	583
31.1 Niobium	583
31.2 Tantalum	586
31.3 Molybdenum	588
31.4 Tungsten	591
31.5 Rhenium	593
31.6 Fabrication	595
31.7 Refractory Metal Protective Coatings	596
Chapter 32 Miscellaneous Nonferrous Metals	597
32.1 Zirconium	597
32.2 Hafnium	598
32.3 Beryllium	598